## RotorSport UK Ltd Service Bulletin

This form is the response from RotorSport UK Ltd either against a problem found in the product in service requiring a containment or rectification action, or as service information for aircraft modification incorporation. Upon completion of the action, the person responsible must enter details into the aircraft logbook/worksheet with the SB and/or CAA MPD (Mandatory Permit Directive) number and sign as normal (see instructions below). For help, contact RotorSport on 44(0)1588 650769, or email info@rotorsport.org.

SB No.: 048 Iss1	CCAR No.: None	Classification:		
		OPTIONAL		
Aircraft type & model (applicability)	Aircraft serial Nos effected	OF FIOI ALL OF		
Deterfue till Celline		DECOMMENDED or		
RotorSport UK Calidus	RSUK/CALS/001, 002, 003	<b>NECOMINIENDED OI</b>		
		MANDATODV		

Problem description & cause of problem if known

The rudder cables of Calidus aircraft exit the keel-tube through two M12-threaded steel inserts. To prevent the risk of long-term wear of the cable strands due to rubbing on the bore of these inserts two small nylon bushes may be fitted. These are easily fitted without any dismantling, provide a visual reference for wear assessment and may be readily replaced.

Action required to implement this service bulletin

- 1. Working underneath the tail of the aircraft, fit the bushes to each side in turn as below:
- 02.06.11

Effective date:

- 2. Use an artists paintbrush dipped in solvent to clean the hexagonal bore of the M12-threaded insert and the adjacent female thread in the control-tube fitting.
- 3. Identify the split in the nylon bush <u>opposite</u> the axial machined groove. Using a small piece of thin metal lever the split of the bush open sufficiently to pass over the cable. Taking advantage of the leading-edge chamfer in the bush fit it over the cable with the circular machined groove outboard of the M12-threaded insert. Push the bush home.



## Circular groove is here

- 4. Protect the cable adjacent to the bush with a loop of masking tape
- 5. Mix a small amount of the adhesive and using a miniature spatula place a fillet of adhesive around the nylon bush and into the visible threads of the control-tube fitting. Ensure that the adhesive fillet enters the machined circular groove of the nylon bush.
- 6. Carefully remove the masking tape and check that no adhesive is present on the cable strands
- 7. After the adhesive has cured (min. <sup>1</sup>/<sub>2</sub>-hour) carefully move the rudder so that the cable becomes slack and smear a small amount of Ballistol oil on to the cable strands that will pass through the bush
- 8. On completion of the installation assess the rudder cable tension by measuring the tensile load required to pull each pedal in turn rearwards from its forward stop. The tensile load should be 5 6Kgf after stiction effect released, for each pedal action.
- 9. In the event of excessive wear the bush can be removed by disrupting the adhesive fillet (with hand tools), pulling the bush from the metal insert and replacing as described above

## RotorSport UK Ltd Service Bulletin

This form is the response from RotorSport UK Ltd either against a problem found in the product in service requiring a containment or rectification action, or as service information for aircraft modification incorporation. Upon completion of the action, the person responsible must enter details into the aircraft logbook/worksheet with the SB and/or CAA MPD (Mandatory Permit Directive) number and sign as normal (see instructions below). For help, contact RotorSport on 44(0)1588 650769, or email info@rotorsport.org.

SB No.: 048 Iss1	CCAR No.: None	Classification:
Aircraft type & model (applicability)	Aircraft serial Nos. effected	RECOMMENDED or
RotorSport UK Calidus	RSUK/CALS/001, 002, 003	MANDATORY





Adhesive fillet in place

View of insert's hexagon socket and control tube's female threads

Parts required to implement this service bulletin 2-off RSD5147 Nylon Bush RSD4232 Araldite epoxy adhesive – as required RSD4655 Amberklene LO30 aerosol solvent RSD4639 Ballistol oil

Effect on Pilots Handbook or Maintenance Manual?

Yes - new text to be incorporated in next revision of Maintenance Manual

Service Bulletin Completion action:

Complete the bulletin implementation worksheet and Issue Permit Maintenance Release Certificate

CAA BCAR A3-7 Authorised Person to certify that the work is completed by writing 'SB-048 Rudder-cable insert bushes fitted" in the aircraft logbook white pages, and record the action in the pink pages entitled 'Aircraft Modifications'. Both entries must be signed by the CAA Authorised Person together with their CAA Authorisation number.

The technical content of this document is approved under the authority of the UK CAA Design Organisation Approval Ref: DAI/9917/06

SB authorised	l by: (name,	signature, and	date of sigr	nature)	
Quality Confe Manager	2019/4	Engineering I	Manager	Chief Test Bilot (if flight performance or safety effect)	Structures (where required $20 - 09 - 2011$
Document completion date:	Issued to:		When	Issuer name	Signature
	Internal	1			
	CAA				
	Owners			•	
	PFA/BM Inspector	AA ate	No		

Page 2 of 3

## RotorSport UK Ltd Service Bulletin

Aircraft serial no.	Service Bulletin			Date raised:			
Registration G-	implementation		Raised by:				
		Worksheet					
Purpose – record service	bulletin im	plementatio	on actions	s taken to	Document reference: SB-048		
inspect aircraft and return	n to service	·					
Maintenance manual refe	erred to and	lissue					
level/date:							
Note; attach SB sheets to	this docun	nent					I
Task		Notes				Eng'r check/date	Inspector check/date
Bushes correctly in place with cured	adhesive						
Masking tape removed and vis that no adhesive contaminatin strands	sible check g cable						
Smear of Ballistol oil on cable	e						
Functional check rudder syste	m OK.						
	Force on left pedal						
		Force on right pedal					
Customer acceptance:			Aircraft hobbs meter reading				
Name.			Confirm logbooks annotated:				
Permit Maintenance Release. The work recorded above has been completed to my satisfaction							
and in that respect the aircraft is considered fit for flight.							
Engineer/Inspector signature				Date of work			
Name <sup>.</sup>				Location when	e work con	nleted	
CAA Authorisation code :						protou	

PLEASE FAX THIS BACK TO 01588650769 (or send by email to info@rotorsport.org)