Title: Cavalon pro low-fuel sensor upgrade					
SB-C-001 lss 1	Related documents Modification: MC-327 CCAR No.: None	Compliance Category:			
Applicability					
Aircraft type & model:	Aircraft serial Nos. affected:				
Cavalon pro	RSUK/CVLN/011				
The maintenance manual to be referenced is this stated or subsequent issue.		RSUK0335 Iss1			

This form is the response from RotorSport UK Ltd either against a problem found in the product in service requiring a containment or rectification action, or as service information for aircraft modification incorporation. For help, contact RotorSport on 44(0)1588 505060, or email compliance@rotorsport.org.

The technical content of this document is approved under the authority of the UK CAA Design Organisation Approval Ref: **DAI/9917/06** 

### Documentation (Service Bulletin Completion action)

a) Entries within the aircraft logbooks, eg CAA BCAR A6-1 Authorised Person to certify that the work is completed by writing '*SB-C-001 Iss 1 Low-fuel sensor upgrade incorporated*' in the aircraft logbook white pages, and record the action in the pink pages entitled 'Aircraft Modifications'. Both entries must be signed by the CAA Authorised Person together with their CAA Authorisation number.

b) Completion of an SB worksheet (attached). This must contain a CRS statement, and a final check item that no tools or equipment have been left within the aircraft

c) Type certificate change application document. This is required where the SB will affect the type certificate limitations, eg airspeed change or MTOW change and enables the owner to request the certificate change required

d) Any other Certificate of Release to Service form requirements.

Document approval signatures					
Engineering Manager	CVE (as required)	Chief Test Pilot (if flight performance or safety effect)	Head of Airworthiness		
	Not required as MC-327 approved	Not required as no flight changes			

#### Reason and overview of the Service Bulletin (cause of problem if known)

Cavalon pro gyroplanes approved under AAN29428 have a low-fuel sensor consisting of a vertical brass tube with cylindrical plastic float that rises and falls with the petrol level inside the right fuel tank. At 5 litres or below a magnet in the float triggers a sensor in the tube to illuminate a warning light on the instrument panel.

RSUK have been made aware of instances of intermittent flashing of the low fuel warning when it is known that the fuel level is above 5 litres. This SB describes a simple modification to the sensor to prevent this nuisance flashing.

#### Manpower estimates

Accomplishment of this Service Bulletin requires the following personnel (i) BCAR A6-1 (para 11) plus type approval Authorised engineer

Estimated man-hours to complete the task as a stand-alone item are; 1hour.

#### Tooling required

Hand tools Headless long-shank M5 stud Tyco terminal extraction tool

#### Weight and Balance Effects

No effect

#### Manuals affected

POH RSUK0334 and AMM RSUK0335 not affected.

### Previous Modifications that affect the SB

None

#### Accomplishment instructions (Action required to implement this bulletin):

Effective date of this SB is 24.06.15. There is no relevant AD or other outside body documentation to be referenced.

#### Instructions

- 1. Park the aircraft on level ground and secure the wheel brakes.
- 2. There is no need to disconnect the battery but the Master Switch must remain off.
- 3. Remove the circular hatch above the right-hand fuel tank. The top of the fuel sensor can be seen beneath. Mark with a felt-tip pen so that it can be replaced in the same position



RH fuel tank hatch Comms panel Centre cover

- 4. Remove the centre cover then the comms panel at the rear of the cockpit and lay to one side, this exposes a blue wiring harness connector. Remove any safety tie then compress the barbs and separate the connector halves
- 5. Using the Tyco pin-removal tool extract the two terminals of the fuel sensor lead (pins 3 and 5)
- 6. The fuel sensor may now be removed from the top of the fuel tank, but the threaded metal inlay inside the tank must be prevented from falling free. Therefore remove only one of the M5 screws and replace with the threaded stud before removing the remaining socket-screws. (When the sensor is lifted away trap the threaded stud with a cable tie or strip of gaffer-tape)



Fuel tank inlay plate

- 7. When surplus fuel has dried-off use a pair of pincers to cut-off the stainless-steel clip at the base of the sensor. Check that the split pin is secure and undamaged
- 8. Check that the float is undamaged and can rise to follow the true fuel level rather than its position being restricted by the clip.
- 9. Clean-up the flange of the sensor
- 10. Ensuring that no debris falls into the tank, clean-up the mating area on top of the tank
- 11. Apply a bead on Loctite 5331 sealant around the underside of the sensor flange and refit the sensor in its original position.
- 12. Replace the M5 socket screws, removing the threaded stud when the metal inlay is secure. Use a film of Loctite 5331 on the socket screws
- 13. Replace the terminal pins and remake the connector. Fit a safety cable tie to the connector and cable-ties as required to the wiring harness
- 14. Replace the fuel-tank hatch, the comms panel and centre cover.



Service Bulletin implementation Worksheet					
Aircraft type:	Serial no:			G-	
Worksheet completed by:				Document ref:	
Worksheet cross-checked by (if applicable):			SB-C-001 Iss1		
Purpose – record service bulletin implementation actions taken to inspect aircraft and return to service.					
Maintenance manual referred-to and issue level:					
Note:	Note: attach SB sheets to this document				
Task	Notes	Eng' check/d	r late	Inspector check/date	
Remove sensor from aircraft					
Remove clip from sensor, inspect OK					
Refit sensor					
Fit safety cable tie on connector					
Replace the fuel tank hatch, the comms panel and the centre cover					
Confirm correct low-level function					

Customer acceptance:				
Name:	Aircraft hobbs meter reading:			
Signature/date:	Confirm logbooks annotated:			
Certificate Release to Service: 'The work recorded has been carried out in accordance with the requirements of the Air Navigation Order for the time being in force and in that respect the aircraft and equipment is considered fit to release to service. I confirm that no tools, equipment or debris have been left in the aircraft'				
Engineer signature and date:	Location where work completed			
CAA CRS Authorisation ref :				