

# AG-MI-2014-06-C-EN -Crimp Connection Relay Cable



## **EFFECTIVE DATE**

#### SUPERSEDES/REPLACES

09.12.2014 N/A (initial issue)

#### **APPLICABILITY**

MTOsport serial numbers M01173 up to and including M01217 and MTOsport, which are retrofitted with main fuse attachement kit - retrofit kit (M.EL452 / after 07.08.2014)

# **COMPLIANCE**

To be performed within the next maintenance event.

#### BACKGROUND

Within Quality checks an inaccurate crimp connection was found on the crimp connector joining the cable from the regulator relay to the fuse box

## **RISK OF NEGLECT**

Failure to comply with this instruction/information will result in

- possible damage to the aircraft
- loss of related warranty

## SCOPE OF WORK

Inspect crimp connection and replace following cables if necessary:

- Main fuse carrier relay (see Fig. 1)
- Relay main fuse carrier (see Fig. 1)

## AFFECTED AREAS

N/A

#### SPECIAL TOOLS & CONSUMABLE MATERIALS

## **PARTS**

For parts please contact AutoGyro: <u>airworthiness@auto-gyro.com</u>

## LABOR AND REQUIREMENTS

To inspect 0.1 h
To accomplish 0.1 h

Task may only be performed by an organization or individual trained and entitled to do 'Line Maintenance' or by the aircraft holder.

## SUPPORT POLICY

Parts f.o.c.

Contact & Info:AutoGyro GmbHairworthiness@auto-gyro.comDornierstr. 14www.auto-gyro.com31137 Hildesheim

AG-MI-2014-06-C-EN Page 1 of 4

## MANUFACTURER INFORMATION



#### REFERENCES

Manufacturer Maintenance Manual (MMM) in latest revision.

#### **DOCUMENTATION**

The accomplishment of this Manufacturer Information, or the decision of its rejection, must be properly documented, if such procedure is required by the relevant authority.

## **Warnings Caution and Notes**

This instruction uses **WARNING**s, **CAUTION**s and **NOTE**s in bold italic letters to indicate especially critical and important instructions. The call-outs appear at the top of the Maintenance Job Card if of general nature or applicable for the complete task, or will directly precede the individual Work Step.

The meaning of each call-out is defined below:

WARNING: A warning means that the neglect of the appropriate procedure or condition could result in personal injury or fatal accidents.

CAUTION: A caution means that the neglect of the appropriate procedure or condition could result in damage to or destruction of equipment.

NOTE: A note stresses the attention for a special circumstance, which is essential to emphasize.

# **Category Codes**

- A Safety critical failure to comply may result in a significant reduction of flight safety, injury or death
- B Important failure to comply may result in reduced safety margin, injury and/or equipment damage
- C Beneficial improves operating behaviour, reliability and/or maintainability

Contact & Info:
airworthiness@auto-gyro.com
Dornierstr. 14
www.auto-gyro.com
31137 Hildesheim



### COMPLIANCE PROCEDURE

## GENERAL, REFERENCES AND REQUIREMENTS

Task may only be performed by an organization trained and entitled to do 'Line Maintenance' or by the aircraft holder.

Secure gyroplane against unauthorized or unintended operation!

Gyroplane must be placed on level ground and restrained (blocks, chocks)

## SPECIAL TOOLS, CONSUMABLE MATERIALS AND PARTS

#### PRECAUTIONS AND SAFETY MEASURES

Battery must be disconnected, see 24-30-00 4-1, steps 1-2

WARNING Electrical shortcuts will produce high current with the risk of personal injury and damage to equipment!

## **PROCEDURES**

- 1 Inspect crimp connection of cables marked in Fig. 1 (Accord: Fig. 2 and 3)
- 2 If crimp connection is wrong, then:
- 3 Open main fuse box by removing cable ties
- 4 Disconnect affected cable(s) from fuse and relay,release affected cable(s) by removing cable ties, replace affected cable(s) by new part(s)
- 5 Assembly in reverse order

### **PARTS LIST**

For parts please contact AutoGyro: <a href="mailto:airworthiness@auto-gyro.com">airworthiness@auto-gyro.com</a>



# **ILLUSTRATIONS**




Fig. 1 - Main fuse carrier




Fig. 2 – Crimp connection correct/wrong (outside)




Fig. 3 – Crimp connection correct/wrong (inside)

Contact & Info: airworthiness@auto-gyro.com www.auto-gyro.com AutoGyro GmbH Dornierstr. 14 31137 Hildesheim