RotorSport UK Ltd Poplar Farm, Prolley Moor, Wentnor, Bishops Castle, Shropshire, SY9 5EJ

Service Information Letter				
SIL-017	Issue: 1	Dated: 19.08.14	CCAR no: 061	
RotorSport aircraft. I	f there is any clarification		e of benefit to pilot owners of the letter, contact RSUK on pleted iaw BP 2.20.	
Aircraft type & model applicability:		Aircraft serial	Aircraft serial numbers affected:	
MT-03, MTOsport, Calidus, Cavalon			All	
Subject: Rotax car	burettor floats			
Safety effect: This SIL-017 is issued to	o warn pilots of possible in-fl	ight engine stoppage or fuel le	eakage.	
Weight and CG effect: Not affected				
	g 914UL engines. It was four		leakage from the carburettor om a carburettor float "sinking"	
carburettor floats. Thes them, thereby maintaining	e floats are manufactured front of a constant fuel level. If ei	4UL engines used in RSUK g om plastic foam and rise to clo ther float sinks, for example b an over-rich mixture. It can ca	ose the shut-off valve above by becoming porous, the fuel	
distributor of the issue. A further information. In the interim Rotax serv that the float bowls are r	A response is awaited and pi	lots should monitor both RSU ettors should be closely follow checked that all floats float to	ved. RotorSport recommend	
None				
Approval Statement: 'The technical co		is approved under the a	-	
		Approval Ref: DAI/9917/	/06'	
None	ook or Maintenance Manu	al:		
	SIL au	uthorised by:		
Quality Control Manager	Engineering Manager	Chief Test Pilot (if fligh performance or safety effe		
Name: G Speich Signature and date:				
Signature and date.	Name: G Shaw Signature and date:	Name: Signature and date:	Name: A Lyons Signature and date:	