## **Service Information Letter**

RotorSport UK Ltd						
Poplar Farm, Prolley Moor, Wentnor, Bi SILNo.: 002 issue 1, dated 12.12.09				shops Castle, Shropshire, UK, SY9 3EJ CCAR No.: None		
Aircraft type & model (applicability) RotorSport UK MT-03 and MTOsport			12.07	Aircraft serial Nos. effected RSUK/MT-03/all and MTOsport/all		
The purpose of this document is to communicate information to pilot owners of RotorSport aircraft that may be of benefit. If there is any clarification required of the content of the letter, contact RSUK on 44(0)1588 650769, or email <a href="mailto:info@rotorsport.org">info@rotorsport.org</a> .						
Subject Rotax annual servicing						Issue date: 12.12.09
Safety effect None						
Weight and CG effect None						
Background: During annual permit inspections the CAA surveyors have noted that on some aircraft the annual service mandated by Rotax on the engine has not been carried out.						
Discussion: The Rotax engine Line Maintenance Manual (latest issue, Sept 01/07) says in Section 05-20 Scheduled Maintenance Checks; 'Periodic inspections are those which must be performed at 50, 100, 200, 600, intervals in accordance with 05-20, sec 2.  This means that for instance that every 100hr. of operation or 1 yr whichever comes first, a 100hr check must be carried out.'						
The CAA consider that therefore the appropriate inspection must be carried out annually, regardless of the number of hours actually flown.						
Recommendation: Ensure that the engine has been serviced in line with the Rotax schedule. All engine manuals were supplied on CD with the aircraft when purchased, replacement copies available from Skydrive.						
References: Rotax Line Maintenance Manual Sept 01/07						
Effect on Pilots Handbook or Maintenance Manual? No						
SIL authorised by: (name, signature, and date of signature)						
Quality Conformand Manager	Eng. Man	neering ager	Chief Test Pilot (if flight performance or safety effect)		Structures (where required)	
Document completion date:	Issued to:	When	Issuer name		Sig	nature
	Internal					
	CAA					
	Owners	1				